Total Quality. Assured.

TEST REPORT

Number: GZHT91300550

Applicant: TRECK SA
SANTA ROSA 5220 SAN
JOAQUIN SANTIAGO CHILE

Date: Nov 20, 2024

Attn:

Sample Description:
One (1) pair of submitted sample said to be Vulcanized Pull on V-Flex metatarsal safety rubber boots in Black/Yellow.

Standard	:	ASTM F1116-14a / ASTM F1117-03(2019)
Size	:	EUR 42
Ref. No.	:	M500
Insert Plate	:	Metallic insert plate
Toe Cap	:	Steel toe
Sole	:	Rubber with steel plate inside
Upper	:	Rubbler
Vamp Lining	:	Polyester
Quarter/Counter Lining	:	Polyester
Tongue	:	N/A
Collar	:	N/A
Insole	:	--
Insock	:	--
Scuff Cap	:	--
Previous Report Number	:	--
Date of Sample Received	:	Oct. 30, 2024
Testing Period	:	Oct. 30, 2024 – Nov. 04, 2024
Date Final Information Confirmed/ Date Payment Received:		Nov. 20, 2024

Test Result Please Refer To Attached Page(S).

Should you have any query on this report, you may contact at gzfootwear@intertek.com

Authorized By:
For Intertek Testing Services Shenzhen Ltd.
Guangzhou Branch

Guiliang Dong
Senior Lab Manager

wq/reneechen

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch
深圳天祥质量技术服务有限公司广州分公司
Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou 510730
广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房
Tel: +86 020-28209114 Postcode:510730
www.intertek.com

TEST REPORT Number: GZHT91300550

Tests Conducted (As Requested By The Applicant)

Dielectric Strength Of Dielectric Footwear (ASTM F1116-14a)

Test Condition:
Test Voltage: 20 000 Voltages (rms value)
Rate Of Rise: (1 000±20) volts
Test Period: 1 to 3 min
Clearances Between Electrodes: 152 mm / 6 inch

Size	Test Period			Requirement	Pass/Fail
	1 min	2 min	3 min		
Left	Withstand	-	-	Min. 1 min	Pass
Right	Withstand	-	-	Min. 1 min	Pass

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch
深圳天祥质量技术服务有限公司广州分公司
Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou 510730
广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房
Tel: +86 020-28209114 Postcode:510730
www.intertek.com



End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch
深圳天祥质量技术服务有限公司广州分公司
Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou 510730
广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房
Tel: +86 020-28209114 Postcode:510730
www.intertek.com